3 Mulberry Close

Material information

3 Mulberry Close Heald Green, Cheadle, SK8 3NJ Kotini has gathered this property information and the sellers have confirmed it to be accurate as of:

11/07/2024 18:01





Introduction

Estate agents are required to provide consumers with 'material information' in property listings to ensure they can make an informed decision when buying a property. Material information is information that the average person needs to make an informed transactional decision#basically, whether a buyer decides to enquire further, view, or buy a property.

The estate agent you're buying from is dedicated to helping people find the right property for them and, as such, has put together this comprehensive summary of the property you've requested to view to help inform your purchasing decision.

If you have any questions about the information contained in this report, please contact your estate agent.



Contents

- %	_
- 7	~

Additional information

Alterations & changes

Boundaries

Completion & moving

Connectivity

Council tax

Delay factors

Displutes & complaints

Electricity

Electrical works

Energy efficiency

Environmental issues

Guarantees, warranties, and indemnity insurances

Heating

Insurance

Listing & conservation

Notices

Other issues

Ownership

Parking

Rights and informal arrangements

Sellers capacity

Services crossing the property

Specialist issues

Type of construction

Water & drainage



Additional information

No

Other material issues

No

Other charges not mentioned elsewhere

No



Not required

Planning permission breaches No	
Unfinished works at the property No	
Unresolved planning issues No	
↓ Structural alterations	
Details of the structural alterations Side elevation extension	
Building regulation approval obtained for the structural changes Yes	
Planning permission approved for the strucutral changes Yes	
Listed building consent obtained for the structural changes Not required	
Structural alterations made to the property Yes	

Details why deed restriction consent wasn"t obtained Freehold
Details why listed building consent wasn"t obtained Not listed
↓ Change of use
Property subject to a change of use No
→ Windows, roof windows, roof lights or glazed doors installations
Details of the windows, roof windows, roof lights or glazed doors installation Main house
Planning permission obtained for the windows, roof windows, roof lights or glazed doors Not required
Windows, roof windows, roof lights or glazed doors installed since 1st April 2002 Yes
Year the installation was completed 2023
Details why planning permission approval wasn't obtained Freehold
Details why deed restriction consent wasn"t obtained Freehold
Deed restriction consent obtained for the windows, roof windows, roof lights or glazed doors Not required

Building regulation approval obtained for the windows, roof windows, roof lights or glazed doors Yes

Listed building consent obtained for the windows, roof windows, roof lights or glazed doors $\ensuremath{\text{Yes}}$

↓ Conservatories

Conservatory added to the property

No



Seller

Boundaries
Boundaries are uniform Yes
Property boundaries differ from the title plan No
Boundaries have been moved No
Proposal to alter the boundaries No
Part of the property are outside the legal ownership of the seller
Part of the property on separate deed No
Adjacent land included in the sale No
Flying freehold at the property No
↓ Boundary ownership
Left boundary

Rear boundary			
Seller			
Right boundary Seller			
Front boundary			
Seller			



Completion & moving

•	
Seller will remove any rubbish	
true	
Seller will replace any light fittings	
true	
Seller will take reasonable care	
true	
Seller will leave all keys	
true	
Property in a chain	
No	
Any dates the seller can't move on	
No	
Sale price sufficient to settle the mortgage	
Yes	
Tes .	
End of section	
End of Section	



Connectivity

Telephone line connected to the property

Yes

Telephone supplier

Sky

↓ Cable & TV

Cable or satellite TV supplier

Sky

Cable or satellite TV connected to the property

Yes

Broadband connection at the property

FTTP (Fibre to the Premises)

Mobile signal issues at the property

No



Council tax

Council Tax band

C

Alterations affecting Council Tax band

No

Annual Council Tax

2020.0



Delay factors

Potential delays to the transaction

No



Past disputes and complaints

No

Potential disputes and complaints

No



Electricity

Electricity meter location

Looking at the left side of the house, on the wall

Mains electricity supplier

Fdf

Property connected to mains electricity

Yes

↓ Solar or photovoltaic panels

Solar or photovoltaic panels installed at the property

No

↓ Other electricity sources

Other sources of electricity connected to the property

No



Electrical works

Electrics tested by a qualified electrician

Yes

Year the electrics were tested

2017

Year the electrical work was carried out

2017

Details of the electrical work

New consumer box

Any electrical works at the property since 2005

Yes



Energy efficiency

Current EPC rating

C

Green deal loan in place

No



Environmental issues

↓ Flooding

Property flooded before

No

Property at risk of flooding

No



Radon test carried out

No

Radon remedial measures on construction

Not known

↓ Coal mining

Coal mining risk

No

↓ Other mining

Other mining risk

No

↓ Coastal erosion

Coastal erosion risk

No

↓ Other

Other environmental risks

No



Guarantees, warranties, and indemnity insurances

Guarantees or warranties available for the property No
New home warranty
No
Guarantes or warranties for roofing work No
Guarantes or warranties for damp proofing treatment No
Guarantes or warranties for central heating and/or plumbing No
Guarantes or warranties for double glazing No
Guarantes or warranties for electrical repair or installation No
Guarantes or warranties for subsidence work No

Guarantes or warranties for solar panels No
Outstanding claims or applications against the guarantees or warranties No
Title defect insurance in place No
Any other guarantees or warranties No
Guarantes or warranties for timber rot infestation treatment No
End of section



Heating
Type of heating system Central heating
Central heating fuel Mains gas
Mains gas, Oil or LPG supplier Edf
Date of installation 11/07/1979
Date of the last service or maintenance 31/10/2023
Was a gas boiler installed after 1st April 2005, or a solid fuel or oil boiler installed after 1st October 2010? Yes
Location of the gas meter Left hand side of the property
Is the heating system in good working order Yes

Other heating features at the property

Double glazing



End of section

Insurance

roperty insured	
es	
/ Insurance concerns	
nsurance previously refused	
0	
nsurance subject to high excesses	
nsurance subject to unusual conditions	
ast insurance claims o	
bnormal rise in insurance premiums	
0	



Listing & conservation

↓ Listing status

Listed building in England or Wales

No

↓ Conservation

Located in a designated conservation area

No

↓ Tree Preservation

Tree preservation order in place

No



Notices

Planning application notice(s) No	
Required maintenance notice(s) No	
Neighbour development notice(s)	
Listed building application notice(s) No	
Infrastructure project notice(s) No	
Party wall act notice(s) No	
Other notices No	
End of section	



Other issues

No	
Crime issues	
No	
Occupied by someone under caution or conviction	
No	
Failed transactions in last 12 months	
Yes	

Details of the failed transactions

Buyer failed to sign contract on the designated date of exchange, reasons still unknown to sellers and legals



Ownership - Freehold

Title number

GM195662

Tenure of the property

Freehold



Parking

	_					
Type	ot	par	king	avai	labi	le

Driveway, On Street

Disabled parking available

Yes

Controlled parking in place

No

Electrical vehicle charging point at the property

Yes



Shared contributions No
Neighbouring land rights No
Public right of way No
Rights of light No
Rights of support No
Rights created through custom No
Rights to take from land No
Mines and minerals under the property No
Church chancel liability No

Other rights

No

Attempts to restrict access

No



Sellers capacity

Capacity

Legal Owner

Sellers capacity details

Maiden name Jennifer Swindells



Services crossing the property

Pipes, wires, cables, drains coming to property	
No	

Pipes, wires, cables, drains from property

No

Formal or informal agreements for services crossing the property

No



Specialist issues

Property treated for dry rot, wet rot or damp No	
Japanese knotweed at the property or neighbouring land No	
Subsidence or structural faults No	
Ongoing health or safety issues at the property No	
Asbestos at the property No	
End of section	



Type of construction

Property is built with standard forms of construction

Yes

Spray foam installed at the property

No

Details of any accessibility adaptations at the property

No accessibility adaptations

→ Building safety

Building safety issues at the property

No



Water & drainage

↓ Water

Location of the water meter

Under stairs

Mains water connected to the property

Yes

Mains water supplier

United utilities

Mains water supply metered

Yes

Location of the stopcock

Under stairs

↓ Drainage

Mains foul drainage connected to the property

Yes

Mains foul drainage supplier

United utilities

Surface water drainage connected to the property

Yes

$\label{eq:maintenance} \textbf{Maintenance} \ \textbf{agreements} \ \textbf{in} \ \textbf{place} \ \textbf{for} \ \textbf{the} \ \textbf{drainage} \ \textbf{system}$

No